

DEGRADATION MODELLING ON THE
INFLUENCE OF MOISTURE CONTENT UPON
BURST CAPACITY OF COMPOSITE REPAIRED
PIPELINE

CHIA SHIN CHIAN

B. ENG (HONS.) CIVIL ENGINEERING

UNIVERSITI MALAYSIA PAHANG



STUDENT'S DECLARATION

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at Universiti Malaysia Pahang or any other institutions.

(Student's Signature)

Full Name : CHIA SHIN CHIAN

ID Number : AA15197

Date :

DEGRADATION MODELLING ON THE INFLUENCE OF MOISTURE CONTENT
UPON BURST CAPACITY OF COMPOSITE REPAIRED PIPELINE

CHIA SHIN CHIAN

Thesis submitted in partial fulfillment of the requirements
for the award of the
B. Eng (Hons.) Civil Engineering

Faculty of Civil Engineering & Earth Resources
UNIVERSITI MALAYSIA PAHANG

MAY 2019

ACKNOWLEDGEMENTS

First and foremost, I would like to express my gratitude to my supervisor, Dr. Lim Kar Sing for his valuable guidance and advices throughout the preparation and completion of this research work. He has supported me, giving his invaluable encouragement, friendships, and knowledge throughout the period of my research study. He always solves my problem for my queries about this research.

Furthermore, I would like to thanks to our coordinator of Final Year Project, Dr. Nurul Nadrah Aqilah binti Tukimat, who had given guidance for us before and ongoing research work and also resolve our documentation problems until the end of the Final Year Project.

Last but not least, I would like to thanks to my parents and friends for giving me fully support and suggestion in the period of research work.

ABSTRAK

Saluran paip adalah cara yang paling digemari untuk mengangkut gas/cecair dalam kuantiti yang besar. Sepanjang perkhidmatan sistem saluran paip keluli, ia digunakan dalam persekitaran yang berbeza yang akan menyebabkan kemerosotan paip keluli. Kini, komposit polimer diperkuat gentian (*FRP*) semakin pesat digunakan untuk membaiki saluran paip keluli dan ia telah terbukti berkesan. Apabila sistem pembaikan komposit terdedah kepada persekitaran yang agresif, terdapat pelbagai faktor yang boleh menjejaskan kekuatan komposit termasuk kelembapan, suhu, keasidan, kebakaran dan ultraviolet. Oleh itu, kajian ini bertujuan untuk menentukan ketahanan komposit serat tikar cincang kaca-epoksi (*chopped strand mat glass fibre/epoxy*) dibawah kesan penyerapan kelembapan dengan menggunakan simulasi analisis unsur terhingga (*FEA*). Komposit direndam dalam air selama 28 hari berturutan pada suhu bilik. Kandungan lembapan komposit berada pada 1.078%, 2.758%, 3.693%, 4.100% dan 4.121% dalam masa 1, 7, 14, 21, dan 28 hari. Terdapat lima model unsur terhingga telah dihasilkan untuk mengkaji kesan kelembapan ke atas tekanan letus. Dapatan dari analisa unsur terhingga (*FE*) menunjukkan sedikit penurunan tekanan letus iaitu 31.663MPa (penurunan sebanyak 0.994%) pada 28 hari dengan kandungan lembapan sebanyak 4.121%. Kekuatan tegangan yang rendah daripada komposit membawa kepada kekurangan sumbangan ketahanan tekanan. Kesan kelembapan komposit kurang jelas ditunjukkan dengan menggunakan serat tikar cincang kaca-epoksi. Walaupun hasil kajian menunjukkan kelembapan tidak banyak memberi kesan terhadap tekanan letus, namun terdapat trend yang menunjukkan penurunan tekanan letus apabila kandungan kelembapan bertambah. Peningkatan kandungan kelembapan akan mengurangkan kekuatan tegangan komposit dan mengakibatkan penurunan tekanan letus. Satu ramalan jangka hayat perkhidmatan paip keluli dibaiki komposit telah dilakukan untuk meramal baki hayat perkhidmatan bagi tujuan menunjukkan bagaimana keputusan dalam kajian ini boleh digunakan oleh pengendali saluran paip. Tekanan letus dijangka berkurangan sebanyak 53.097% berbanding dengan model kawalan iaitu dari 31.981MPa kepada 15MPa selepas 178 hari.

ABSTRACT

Pipelines are most favored mode of transportation of gas/liquid in large quantities. Along the service life of steel pipeline system, it exerted in different condition of surrounding which cause deterioration of steel pipeline. There is a rapid growth in the application of Fibre-Reinforced Polymer (FRP) composites wrap where the method has been proven effective for repairing steel pipelines. When composite repair system exposed to aggressive environment, there are various factors which may affect the strength of composite include moisture, temperature, acidity, fire and ultraviolet. This study aims to determine the durability of chopped strand mat glass fibre/epoxy composite under the effect of moisture absorption using finite element analysis (FEA) simulation. The composite was immersed into water for 28 days at room temperature. The moisture contents of composite were 1.078%, 2.758%, 3.693%, 4.100%, and 4.121% on immersion time of 1, 7, 14, 21, and 28 days, respectively. Five finite element models were developed to study the moisture effect toward burst pressure. The FE result shows a slightly drop for burst pressure on 28-days which was 31.663MPa (0.994% drop) with moisture content of 4.121%. The low tensile strength of composite lead to less contribution toward stress sustainability. The moisture effect of composite was not obviously shown by using chopped strand mat glass fibre-epoxy. Although the result shows not much effect of moisture toward the burst pressure, but there was a trend shows the decreasing of burst pressure when moisture content increases. The increase of moisture content decreases the tensile strength of composite and resulted in decreasing of burst pressure. A prediction of long-term service life of composite repaired steel pipe was performed to forecast its remaining service life to demonstrate how the results in this study can be used by the pipeline operators. The burst pressure was predicted to reduce by 53.097% compared to control model which drop from 31.981MPa to 15MPa after 178 days.

TABLE OF CONTENT

DECLARATION

TITLE PAGE

ACKNOWLEDGEMENTS **ii**

ABSTRAK **iii**

ABSTRACT **iv**

TABLE OF CONTENT **v**

LIST OF TABLES **viii**

LIST OF FIGURES **ix**

LIST OF SYMBOLS **x**

LIST OF ABBREVIATIONS **xi**

CHAPTER 1 INTRODUCTION **1**

1.1 Overview 1

1.2 Problem Statement 2

1.3 Objective of study 3

1.4 Scope of the study 4

1.5 The importance of the study 4

CHAPTER 2 LITERATURE REVIEW **5**

2.1 Introduction 5

2.2 Overview 5

2.3 Conventional Pipeline Repair Techniques 6

2.4 Composite Repair System 8

2.4.1	Fibre Reinforcement	10
2.4.2	Resin Matrix	11
2.5	Degradation of FRP composite	12
2.5.1	Moisture	13
2.5.2	Thermal effect	13
2.6	Challenges of using composite repair system	14
2.7	Concluding remarks	15
CHAPTER 3 RESEARCH METHODOLOGY		17
3.1	Introduction	17
3.2	Overview of overall research methodology	17
3.3	Stage 1: Developed composite repaired pipe base model	18
3.3.1	Modelling defect steel pipe	20
3.3.2	Input material properties, load and boundary condition	21
3.3.3	Meshing steel pipe	22
3.3.4	Implementation and validation of defective pipe models	23
3.3.5	Modelling composite repaired steel pipe	24
3.3.6	Modelling of Putty	24
3.3.7	Modelling of composite wrap	26
3.3.8	Execution and validation of composite repaired pipe models	28
3.4	Stage 2: Parametric study	28
3.5	Concluding remarks	30
CHAPTER 4 RESULTS AND DISCUSSION		31
4.1	Introduction	31
4.1	Validation of base model	31

4.2	Parametric study	32
4.2.1	Moisture absorption of chopped mat glass fibre/epoxy composite	32
4.2.2	Tensile strength of chopped mat glass fibre/epoxy composite	33
4.2.3	Stress contour plots	34
4.2.4	Burst capacity of chopped mat glass fibre/epoxy composite repaired pipe	38
4.3	Concluding remarks	42
CHAPTER 5 CONCLUSION AND RECOMMENDATION		43
5.1	Overview	43
5.2	Conclusion	44
5.3	Significant of research contribution	45
5.4	Recommendations	46
REFERENCES		47

LIST OF TABLES

Table 3.1	Material propeties of composite wrap	28
Table 4.1	Properties of chopped strand mat glass fibre/epoxy when expose to moisture in duration of 1,7,14,21 and 28 days	32

LIST OF FIGURES

Figure 2.1	Compound box	6
Figure 2.2	Clamp made of fabric	7
Figure 2.3	Steel sleeve repairs	8
Figure 2.4	Infilled fibre composite repair system	9
Figure 2.5	Properties of selected commercial reinforcing fibres	11
Figure 2.6	Schematic representation of (a) thermoplastic and (b) thermoset	12
Figure 2.7	Summarization of current issues by using composite repaired system.	16
Figure 3.1	Flow chart of overall research methodology	18
Figure 3.2	Flow chart of research methodology for stage 1.	20
Figure 3.3	Geometry of bare pipe and defect pipe	21
Figure 3.4	Engineering stress-strain and true stress-strain curve	22
Figure 3.5	internal pressure and boundary condition of model.	22
Figure 3.6	Meshing process of defect pipe until achieve structural mesh	23
Figure 3.7	Meshed bare pipe and defect pipe	24
Figure 3.8	Model of putty	25
Figure 3.9	Steps for translation of putty location	26
Figure 3.10	Meshed putty	26
Figure 3.11	Flow chart of research methodology for stage 2.	29
Figure 4.1	Water uptake of chopped strand mat glass fibre/epoxy immersed at room temperature	33
Figure 4.2	Stress contour plot of composite repaired pipe and each component for day-1	35
Figure 4.3	Stress contour plot of composite repaired pipe and each component for day-7, day-14 and day-21.	36
Figure 4.4	Stress contour plot of composite repaired pipe and each component for day-28.	36
Figure 4.5	Stress contour plot of composite immersed in water at room temperature apply for composite repaired steel pipe for 28 days.	37
Figure 4.6	Effect of moisture content of composite wrap towards tensile strength.	39
Figure 4.7	Effect of moisture content upon burst pressure of composite repaired steel pipe of day-1, day-7 day-14, day-21 and day-28.	40
Figure 4.8	Predict service life of composite repaired steel pipe on moisture effect.	41

LIST OF SYMBOLS

E	Young's Modulus
G	Tensile modulus
ν	Shear modulus

LIST OF ABBREVIATIONS

PG&E	Pacific Gas and Electric Company
FRP	Fibre-Reinforced Polymer
UV	Ultraviolet
UTS	Ultimate tensile strength
TTS	Time-temperature superposition
FEA	Finite Element Analysis
USA	The United States of America
BP	Burst pressure
FE	Finite Element

CHAPTER 1

INTRODUCTION

1.1 Overview

Pipelines function as blood vessels serving to transport life-necessities such as water or natural gas, oil and to take away life waste like sewage (Central Intelligence Agency, 2018). Pipeline are also considered to be the most favoured mode of transportation of gas/liquid in large quantities (Kishawy and Gabbar, 2010). According to a database published by the United State of America's Central Intelligence Agency, there are over one million kilometres of pipelines laid around the world to transport oil and natural gas (Central Intelligence Agency, 2018). Along the service life of steel pipeline system, it exerted in different condition of surrounding such as aggressive environments with high pressures and high temperatures which cause deterioration of steel pipeline. The degradation of pipeline may lead to leaking, fire and explosion. In regard to urban natural gas pipeline accidents, corrosion is one of the major causes (Muhlbauer, 2004). Pipeline failure due to corrosion attack can cause hazards involving multiple fatalities, serious financial loss, bad economic implications, and significant environmental damage (Yahaya et al., 2009).

As reported by the National Transportation Safety Board (2011), an explosion of a natural gas pipeline in San Bruno, California, owned by Pacific Gas and Electric Company (PG&E), killed eight people, injured 58 others, destroyed 38 houses, and damaged 70 more in a residential neighbourhood. According to The Star Online, there is a fire broke out on Tukai B drilling platform with 60m-deep underwater inside the vicinity of the Tukai Oilfield, located 31km from the Miri shoreline that belonging to Petronas in deep waters in the South China Sea. There were 16 peoples on board doing maintenance work on the platform during the fire had been successfully evacuated and

the fire was doused in an hour (Stephen, 2012). In preventing the risk and hazardous to occur, maintenance, checking by using pigging and safety are very significant to carry out. There is more than 35% of Malaysia local onshore pipeline are more than 30 years old (Petronas Gas Berhad, 2014). Therefore, in order to ensure the serviceability of pipeline system to continue safely, rehabilitation of structurally compromised pipelines is needed.

There is a wide range of rehabilitation techniques and repair methods available for onshore and offshore pipelines. To repair corroded steel pipeline, several method can be used such as, applying grout, installing full-encirclement steel sleeve or steel clamp, or remove the entire corroded pipe to replace a new pipe if condition is critical (Noor et al., 2016). Apart from that, there is a rapid growth in the development and application of FRP composites wrap recently where the method has been proven effective for repairing steel structures such as risers and pipelines (Duell et al., 2008; Leong et al., 2011; Alexander, 2014; Chan et al., 2015).

1.2 Problem Statement

Fibre-Reinforced Polymer (FRP) composite wrap is increasingly used as rehabilitation technique of pipeline system. In order to optimise the design of composite repair system, the load bearing capacity of FRP composite wrap is important. However, the performances of FRP composite wrap in various environment conditions are not fully understood. Their durability and integrity in various service environments depends of the response of its constituents i.e., fibre, polymer matrix, and the existing interface between the fibre and polymer matrix, in that particular environment (Sethi and Ray, 2015). When composite repair system exposed to environment, there are various factors which may affect the strength of FRP composite wrap over time include UV, temperature, acidity, alkalinity, humidity, fire and moisture. According to Keller et al. (2013), carbon fibre/epoxy matrix composites that exposed to water for over 18 months are conservative for 50 years design life with maximum loading of 16% and 65% ultimate tensile strength (UTS) for time-temperature superposition (TTS) high-crimp composite and tensile creep test, respectively.

From the past literature, there is limited information regarding the load bearing capacity of the FRP composite wrap that can help in predict how long it can sustain steel pipe until failure. The lack of durability data of FRP composite wrap not only lead to use of high factors of safety in design such as 4-6 in marine industry and 8-12 in the area of tanks and pipe (Helbling et al., 2006), it also increase the cost of overall repair system. The environmental condition that the pipeline structure located is significant to the degradation of FRP composite wrap. However, the lifetime durability validated data and knowledge are limited that make the research difficult. In this study, collection, assessment and appropriate documentation of available data of degradation FRP composite wrap were reviewed from previous research that used in civil structure. The parameters investigated in this study are glass fibre-reinforced polymer in epoxy matrix composite and the effect of moisture environment condition towards the strength degradation of the FRP composite. All the degradation data of FRP composite strength collected from previous research were utilised in Finite element analysis to predict the burst pressure and service life of steel pipe that are repaired by FRP composite.

1.3 Objective of study

This study aims to investigate the durability of FRP composite wrap under the effect of moisture content over time upon burst capacity of composite repaired pipeline by finite element analysis (FEA). The objectives of this study are:

1. To investigate of the strength degradation of FRP composite wrap under the effect of moisture variation.
2. To determine the burst pressure of composite repaired pipeline subjected to degradation of composite wrap under different moisture condition.
3. To determine the remaining service life of pipeline repaired by FRP composite wrap.

REFERENCES

- 3Xengineering. 2016. *STOPKiT* [Online]. Available: <http://3xengineering.com/> [Accessed].
- Alexander, C. 2014. The Role of Composite Repair Technology in Rehabilitating Piping and Pipelines. V06AT06A025.
- Alexander, C.R. 2007. *Development of a composite repair system for reinforcing offshore risers*, Texas A&M University.
- Antaki, G.A. 2003. *Piping and Pipeline Engineering: Design, Construction, Maintenance, Integrity, and Repair*, New York, U.S.A., Marcel Dekker, Inc.
- Antoon, M. and Koenig, J. 1980. The structure and moisture stability of the matrix phase in glass-reinforced epoxy composites. *Journal of Macromolecular Science—Reviews in Macromolecular Chemistry*, 19, 135-173.
- Apicella, A., Migliaresi, C., Nicodemo, L., Nicolais, L., Iaccarino, L. and Roccotelli, S. 1982. Water sorption and mechanical properties of a glass-reinforced polyester resin. *Composites*, 13, 406-410.
- Azraai, S.N.A., Lim, K.S., Yahaya, N. and Noor, N. 2015. *Infill Materials of Epoxy Grout for Pipeline Rehabilitation and Repair*.
- Béland, S. 1990. *High performance thermoplastic resins and their composites*, New Jersey, Noyes Publications.
- Bonniau, P.a. and Bunsell, A.R. 1981. A comparative study of water absorption theories applied to glass epoxy composites. *Composite Materials*, 15, 272-293.
- Carbas, R., Da Silva, L., Marques, E. and Lopes, A. 2013. Effect of post-cure on the glass transition temperature and mechanical properties of epoxy adhesives. *Adhesion Science Technology*, 27, 2542-2557.
- Central Intelligence Agency 2018. The World Factbook Field Listing: Pipelines.
- Cercone, L. and Lockwood, J.D. 2005. Review of FRP composite materials for pipeline repair. *Pipelines 2005: Optimizing Pipeline Design, Operations, and Maintenance in Today's Economy*.
- Chan, P.H., Tshai, K.Y., Johnson, M., Choo, H.L., Li, S. and Zakaria, K. 2015. *Burst strength of carbon fibre reinforced polyethylene strip pipeline repair system - A numerical and experimental approach*.
- Chin, J.W., Nguyen, T. and Aouadi, K. 1999. Sorption and diffusion of water, salt water, and concrete pore solution in composite matrices. *Journal of Applied Polymer Science*, 71, 483-492.
- Duell, J.M., Wilson, J.M. and Kessler, M.R. 2008. Analysis of a carbon composite overwrap pipeline repair system. *International Journal of Pressure Vessels and Piping*, 85, 782-788.
- Ellyin, F. and Maser, R. 2004. Environmental effects on the mechanical properties of glass-fiber epoxy composite tubular specimens. *Composites Science Technology*, 64, 1863-1874.
- Epoxy Technology Inc 2012. Tg - Glass Transition Temperature for Epoxies.

- Freire, J., Vieira, R., Diniz, J. and Meniconi, L. 2007. Part 7: Effectiveness of composite repairs applied to damaged pipeline. *Experimental Techniques*, 31, 59-66.
- Gaur, U., Chou, C. and Miller, B. 1994. Effect of hydrothermal ageing on bond strength. *Composites*, 25, 609-612.
- Geraghty, M., Pridmore, A. and Sanchez, J. 2011. Transitioning from leak detection to leak prevention: proactive repair of steel pipelines using fiber reinforced polymer (FRP) composites. *Pipelines 2011: A Sound Conduit for Sharing Solutions*.
- Giancaspro, J.W., Papakonstantinou, C.G. and Balaguru, P. 2010. Flexural response of inorganic hybrid composites with E-glass and carbon fibers. *Journal of Engineering Materials*, 132, 021005.
- Gibson, A. 2003. *The cost effective use of fibre reinforced composites offshore*, HSE Books Norwich, UK.
- Gopalan, R., Somashekar, B. and Dattaguru, B. 1989. Environmental effects on fibre—Polymer composites. *Polymer degradation stability*, 24, 361-371.
- Hassan, Z. 2008. Introduction: The Oil and Gas Industry. *BEng. Petroleum Technology*. University Malaysia Pahang.
- Helbling, C., Abanilla, M., Lee, L. and Karbhari, V.M. 2006. Issues of variability and durability under synergistic exposure conditions related to advanced polymer composites in the civil infrastructure. *Composites Part A: Applied Science and Manufacturing*, 37, 1102-1110.
- Herrera-Franco, P. and Drzal, L. 1992. Comparison of methods for the measurement of fibre/matrix adhesion in composites. *Composites*, 23, 2-27.
- Ishai, O. 1975a. Environmental effects on deformation, strength, and degradation of unidirectional glass - fiber reinforced plastics. II. Experimental study. *Polymer Engineering Science*, 15, 486-490.
- Ishai, O. 1975b. Environmental Effects on Deformation, Strength, and Degradation of Unidirectional Glass Fiber Reinforced Plastics. I. Survey. *Polymer Engineering Science*, 15, 491-499.
- Jamal, H. 2017. *Engineering Stress and Strain Curve Diagram* [Online]. aboutCivil.com. Available: <https://www.aboutcivil.org/engineering-stress-strain-curve.html> [Accessed].
- Jeffrey, K.J.T., F, T. and Rahman, M. 2011. *Residual Strength of Chop Strand Mats Glass Fiber/Epoxy Composite Structures: Effect of Temperature and Water Absorption*.
- Jiang, X., Kolstein, H. and Bijlaard, F.S. 2013. Moisture diffusion in glass–fiber-reinforced polymer composite bridge under hot/wet environment. *Composites Part B: Engineering*, 45, 407-416.
- Joshi, S.V., Drzal, L., Mohanty, A. and Arora, S. 2004. Are natural fiber composites environmentally superior to glass fiber reinforced composites? *Composites Part A: Applied science manufacturing*, 35, 371-376.

- Karbhari, V. 2007. Fabrication, quality and service-life issues for composites in civil engineering. *Durability of composites for civil structural applications*. Elsevier.
- Keller, M., D. Jellison, B. and Ellison, T. 2013. *Moisture effects on the thermal and creep performance of carbon fiber/epoxy composites for structural pipeline repair*.
- Khalid, A.A., Sahari, B.B. and Khalid, Y.A. 2004. Environmental effects on the progressive crushing of cotton and glass fibre/epoxy composite cones. *Advanced in Materials Processing and Technologies*, p.p 680-689.
- Kini, A., Shettar, M., Sharma, S.S. & Hiremath, P. 2018. *Behavioral Study of Mechanical Properties of Glass Fiber-Epoxy Composites under Moisture Absorption*.
- Kishawy, H.A. and Gabbar, H.A. 2010. Review of pipeline integrity management practices. *International Journal of Pressure Vessels and Piping*, 87, 373-380.
- Lau, K.t. and Zhou, L.-m. 2001. *The mechanical behavior of composite-wrapped concrete cylindrs subjected to uniaxial compression load*.
- Leong, A.Y.L., Leong, K.H., Tan, Y.C., Liew, P.F.M., Wood, C.D., Tian, W. and Kozielski, K.A. 2011. *Overwrap composite repairs of offshore risers at topside and splash zone*.
- Li, M. 2000. *Temperature and moisture effects on composite materials for wind turbine blades*. Montana State University, Bozeman.
- Lim, K.S. 2017. *Behaviour of Repaired Composite Steel Pipeline Using Epoxy Grout as Infill Material*. Doctor of Philosophy (Civil Engineering) Structure & Material Universiti Teknologi Malaysia.
- Liu, H. 2003. *Pipeline Engineering*, New York, U.S.A., Lewis Publishers.
- Lukács, J., Nagy, G., Török, I., Égert, J. & Pere, B. 2010. Experimental and numerical investigations of external reinforced damaged pipelines. *Procedia Engg*, 2, 1191-1200.
- Mallick, P.K. 2007. *Fiber-reinforced composites: materials, manufacturing, and design*, CRC press.
- Melander, A. and Österberg, J. 2016. *Fiber Reinforced Polymers for Rehabilitation of Pipelines*. Master's thesis, Chalmers University of Technology.
- Muhlbauer, W.K. 2004. *Pipeline Risk Management Manual*, Gulf Publishing Company.
- Mustaffa, Z. 2011. System reliability assessment of offshore pipelines.
- National Transportation Safety Board. 2011. *Board Meeting : Pacific Gas and Electric Company Natural Gas Transmission Pipeline Rupture and Fire, San Bruno, California* [Online]. Available: https://www.nts.gov/news/events/pages/pacific_gas_and_electric_company_natural_gas_transmission_pipeline_rupture_and_fire_san_bruno_california.aspx [Accessed 10 November 2018].
- Noor, N., Azraai, S.N.A., Lim, K.S. and Yahaya, N. 2015. *An Overview of Corroded Pipe Repair Techniques Using Composite Materials*.
- Noor, N., Lim, K.S., Yahaya, N. and Azraai, S.N.A. 2016. *Systems for Repair and Rehabilitation of Corroded Oil & Gas Pipelines*.

- Ochola, R., Marcus, K., Nurick, G. and Franz, T. 2004. Mechanical behaviour of glass and carbon fibre reinforced composites at varying strain rates. *Composite Structures*, 63, 455-467.
- Palmer-Jones, R. and Paisley, D. 2000. Repairing internal corrosion defects in pipelines-a case study. The Proceedings of the 4th International Pipeline Rehabilitation and Maintenance Conference, September 2000 Prague.
- Patel, M.H. 1995. *An Introduction to Offshore Engineering: Off-shore Engineering Handbook Series*, London, Bentham Press.
- Patrick, A.J. 2004. Composites-case studies of pipeline repair applications. *Pigging Products Services Association*.
- Petronas Gas Berhad 2014. Pipeline System Listing. Transmission Operation Division.
- Picard, D., Hudson, W., Bouquier, L., Dupupet, G. and Zivanovic, I. 2007. Composite carbon thermoplastic tubes for deepwater applications. Offshore technology conference, 2007 Houston, Texas.
- Ray, B. 2005. Freeze–Thaw response of glass–Polyester composites at different loading rates. *Journal of reinforced plastics composites*, 24, 1771-1776.
- Ray, B. 2006. Temperature effect during humid ageing on interfaces of glass and carbon fibers reinforced epoxy composites. *Journal of colloid interface science*, 298, 111-117.
- Sala, G. 2000. Composite degradation due to fluid absorption. *Composites Part B: Engineering*, 31, 357-373.
- Schutte, C.L. 1994. Environmental durability of glass-fiber composites. *Materials Science Engineering: R: Reports*, 13, 265-323.
- Seica, V.M. and Packer, A.J. 2007. FRP materials for the rehabilitation of tubular steel structures, for underwater applications. *Comp Struct*, 80, 440-450.
- Sen, R. and Mullins, G. 2007. Application of FRP composites for underwater piles repair. *Composites Part B: Engineering*, 38, 751-758.
- Sereir, Z., Adda-Bedia, E. and Tounsi, A. 2005. Effects of the accelerated moisture diffusivity on the hygrothermal behavior on a laminated plate with symmetrical environmental conditions. *Journal of Thermal stresses*, 28, 889-910.
- Sethi, S. 2014. *Environmental Degradation Study of FRP Composites Through Evaluation of Mechanical Properties*.
- Sethi, S. and Ray, B.C. 2015. Environmental effects on fibre reinforced polymeric composites: Evolving reasons and remarks on interfacial strength and stability. *Advances in Colloid and Interface Science*, 217, 43-67.
- Shamsuddoha, M. 2014. *Behaviour of infilled rehabilitation system with composites for steel pipe*. University of Southern Queensland.
- Shamsuddoha, M., Islam, M.M., Aravinthan, T., Manalo, A. and Lau, K.-t. 2013. Characterisation of mechanical and thermal properties of epoxy grouts for composite repair of steel pipelines. *Materials Design*, 52, 315-327.
- Shilpa, K. 2010. *Damage and Degradation Study of FRP Composite*. Metallurgical and Materials Engineering, National Institute of Technology.
- Shouman, A. and Taheri, F. 2011. Compressive strain limits of composite repaired pipelines under combined loading states. *Composite Structures*, 93, 1538-1548.

- Simulia. 2012. Abaqus 6.12/CAE User's Manual. Providence. RI, U.S.A.
- SMC Sweden. 2016. *Läcktätningar* [Online]. [Accessed].
- Stephen, T. 2012. Five hurt in oil drilling platform fire. *The Star Online*, 12 June 2012.
- Tanaka, K., Minoshima, K., Grela, W. and Komai, K. 2002. Characterization of the aramid/epoxy interfacial properties by means of pull-out test and influence of water absorption. *Composites Science Technology*, 62, 2169-2177.
- Tounsi, A. and Amara, K. 2005. Stiffness degradation in hygrothermal aged cross-ply laminate with transverse cracks. *AIAA journal*, 43, 1836-1843.
- Tounsi, A., Amara, K. and Adda-Bedia, E. 2005. Analysis of transverse cracking and stiffness loss in cross-ply laminates with hygrothermal conditions. *Computational materials science*, 32, 167-174.
- Wagner, H. and Lustiger, A. 1994. Effect of water on the mechanical adhesion of the glass/epoxy interface. *Composites*, 25, 613-616.
- Wonderly, C., Grenestedt, J., Fernlund, G. and Čěpus, E. 2005. Comparison of mechanical properties of glass fiber/vinyl ester and carbon fiber/vinyl ester composites. *Composites Part B: Engineering*, 36, 417-426.
- Xu, Z. and Ashbee, K. 1994. Photoelastic study of the durability of interfacial bonding of carbon fibre-epoxy resin composites. *Journal of materials science*, 29, 394-403.
- Yahaya, N., Mat Din, M. and Mohd Nor, S.H. 2009. *Prediction of CO₂ corrosion growth in submarine pipelines*.
- Zhou, J. and Lucas, J.P. 1999. Hygrothermal effects of epoxy resin. Part I: the nature of water in epoxy. *Polymer*, 40, 5505-5512.